

2016 ROAD SURFACE RATING & SUGGESTED REPAIR

- Repair Method
- Reclamation

Mill and Overlay
- Surface Treatment

Crack Seal


Defer Maintenance

Parcel Line

Town of Franklin



0 0.25 0.5
Kilometers
0 0.25 0.5
Miles



In maintaining its GIS Data, the Town of Franklin has made every effort to ensure the accuracy, currency and reliability of the content thereof, however, errors can occur. It is expressly understood and agreed that in producing this information, the Town of Franklin, its officials, agents, servants and employees does not warrant or guarantee the information it has provided, nor does it accept responsibility for any errors contained therein. In no event will the Town of Franklin, its officials, agents, servants and employees be deemed or held obligated, liable, or accountable for any loss or damage incurred or resulting from the use of the information provided.