

Environmental Reporting for Nu-Style Property 21 Grove Street & 87 Old Grove Street, Franklin, MA

Unless otherwise noted, all reports developed by
Fuss & O'Neill, Inc., Providence, RI

Phase III Identification, Evaluation, and Selection of Comprehensive Remedial Action Alternatives and Remedial Action Plan, Former Nu-Style Property, 21 Grove Street, Franklin MA. RTN 2-16694. Verdantas LLC, May 2024

Phase II Comprehensive Site Assessment Report, Former Nu-Style Property, 21 Grove Street, Franklin MA. RTN 2-16694. Verdantas LLC, February 2024

Permanent Solution with Conditions – Partial for 87 Grove Street, Franklin, MA. RTN 2-16694. Tata & Howard, October 2015

Results of Passive Soil Gas Survey
87 Grove Street, Franklin, MA
Tata & Howard, March 2015

Soil Vapor Intrusion Study Report
Former Nu-Style Facility
87 Grove St. Franklin, MA
Environmental Corp of America,
December 2014

Targeted Brownfields Assessment
Nu Style, Franklin MA
EPA Task Order No. 0078-SI-BZ-0100
Nobis Engineering, Inc.
September 2013

Release Abatement Measure
Completion Report
Former Nu-Style Property
87 Grove St. Franklin, MA
RTN 2-16694. April 2013

Release Abatement Measure
Former Nu-Style Property, 87 Grove Street
Franklin, MA. May 2013

Segregation and Demolition Plan for
Asbestos, Lead and Hazardous Building
Materials - Former Nu-Style Facility
Town of Franklin, MA
October 2011

Site-Specific QAPP Modification
Supplemental Building Materials Sampling
Former Nu-Style Facility, 87 Grove Street
Franklin, Massachusetts
USEPA QA RFA Tracking # 08312
June 2011

Site-Specific Quality Assurance Project Plan
Addendum – Revision 1.0
Building Materials Investigation
Former Nu-Style Facility
Franklin, MA
QA Tracking #: 08132
May 2011

Analysis of Brownfields Cleanup Alternatives
Former Nu-Style Property, Lot 27
87 Grove Street
Franklin, Massachusetts
Mass DEP RTN 2-16694
May 2011

Site-Specific Quality Assurance Project Plan
Addendum - Revision 0.0
Building Materials Assessment
Former Nu-Style Facility
Franklin, Massachusetts
USEPA QA Tracking #: 08312
April 2011

Community Relations Plan
Former Nu-Style Property, Lot 27
87 Grove Street
Franklin, Massachusetts
March 2011

Phase II Site Assessment Report
Former Nu-Style Property
RTN 2-16694
87 Grove Street (Lot 22 & 27)
Franklin, MA
September 2010

Limited Site Assessment Report
Former Nu-Style Property
RTN 2-0016694
87 Grove Street (Lot 22 & 27)
Franklin, MA
July 2009

Hazardous Building Materials Inspection
Former Nu-Style Building
87 Grove Street
Town of Franklin
Franklin, Massachusetts
March 2009

Phase I- Initial Site Investigation Report
Former Nu-Style Property
87 Grove Street (Lot 22 & 27)
Franklin, MA
RTN 2-16694
May 2008

Phase II Environmental Site Assessment
Addendum
Former Nu-Style Property
RTN 2-0016694
87 Grove Street (Lot 22 & 27)
Franklin, MA
February 2008

Phase II Site Assessment Report
Former Nu-Style Property
RTN 2-0016694
87 Grove Street (Lot 22 & 27)
Franklin, MA
February 2008

Phase II Environmental Site Assessment Report
Former Nu-Style Company, Inc. Facility
87 Grove Street (Lot 22 & 27)
Franklin, MA
September 2007

Quality Assurance Project Plan Addendum
Revision 3.0
Former Nu-Style Company, Inc. Facility
RFA #07011
87 Grove Street (Lot 22 & 27)
Franklin, MA
September 2007

UST Closure Assessment Report
Former Nu-Style Company, Inc.
Franklin, MA
July 2007

Chapter 21E Site Evaluation of 87 Grove Street
for National Bank of Milford, Massachusetts
IES, Inc. Environmental Consultants
IES Job No, 789-374
January 1990

IES, Inc. Environmental Consultants collected soil samples from four additional borings (B1A through B-4A) to assess whether releases associated with underground storage tanks had occurred. Only a portion of this document is available and is located at the Franklin Fire Department. (July 1991).

Quality Assurance Project Plan Addendum
Revision 2.0
Former Nu-Style Company, Inc. Facility
RFA #07011
87 Grove Street (Lot 22 & 27)
Franklin, MA
March 2007

Phase I Environmental Site Assessment
Former Nu-Style Company, Inc.
87 Grove Street (Lot 22 & 27)
Franklin, MA
February 2007

Phase II Environmental Site Assessment Report
Former Nu-Style Company, Inc.
87 Grove Street (Lot 22 & 27)
Franklin, MA
January 2007

Quality Assurance Project Plan
Revision 1.0
Phase II Site Assessment
Former Nu-Style Company, Inc. Facility
RFA #07011
87 Grove Street (Lot 22 & 27)
Franklin, MA
October 2006

Quality Assurance Project Plan
Revision 0.0
Phase II Site Assessment
Former Nu-Style Company, Inc. Facility
87 Grove Street (Lot 22 & 27)
Franklin, MA
September 2006

Phase I Environmental Site Assessment
Former Nu-Style Company, Inc. Facility
87 Grove Street (Lot 22 & 27)
Franklin, MA
May 2006